



**Public Utility Commission** 

550 Capitol Street NE, Suite 215 Mailing Address: PO Box 2148 Salem, OR 97308-2148 Consumer Services 1-800-522-2404 Local: 503-378-6600 Administrative Services 503-373-7394

March 6, 2009

Via Electronic Filing and U.S. Mail

OREGON PUBLIC UTILITY COMMISSION ATTENTION: FILING CENTER PO BOX 2148 SALEM OR 97308-2148

## RE: **Docket No. UE 196** - In the Matter of PORTLAND GENERAL ELECTRIC COMPANY Application to Amortize the Boardman Deferral.

Enclosed for filing in the above-captioned docket is the Public Utility Commission Staff's Response Testimony. This document is being filed by electronic mail with the PUC Filing Center.

*(s/ Kay Barnes* Kay Barnes Regulatory Operations Division Filing on Behalf of Public Utility Commission Staff (503) 378-5763 Email: kay.barnes@state.or.us

cc: UE 196 Service List - parties

## PUBLIC UTILITY COMMISSION OF OREGON

UE 196

## STAFF RESPONSE TESTIMONY OF

## Ed Durrenberger

## In the Matter of PORTLAND GENERAL ELECTRIC COMPANY Application to Amortize the Boardman Deferral.

March 6, 2009

CASE: UE 196 WITNESS: Ed Durrenberger

## PUBLIC UTILITY COMMISSION OF OREGON

**STAFF EXHIBIT 300** 

**Response Testimony** 

March 6, 2009

Docket UE 196

# Q. PLEASE STATE YOUR NAME, OCCUPATION, AND BUSINESS ADDRESS.

A. My name is Ed Durrenberger. I am a Senior Utility Analyst employed by the
Public Utility Commission. I have provided Direct and Surrebuttal Testimony in
this proceeding entered as Exhibit Staff/100/Durrenberger and Exhibit Staff/
200/ Durrenberger. My Witness Qualification Statement is found in Exhibit
Staff/101.

#### 8 Q. DID YOU PREPARE AN EXHIBIT FOR THIS DOCKET?

9 A. Yes, I have included exhibits in Direct and Surrebuttal testimony previously
10 submitted in this docket but I will not be including any exhibits in this Response
11 Testimony.

#### 12 Q. COULD YOU PLEASE SUMMARIZE THIS RESPONSE TESTIMONY?

13 A. Yes. The Commission determined that the record was inadequate to reach a 14 determination of prudence on the part of Portland General Electric Company 15 (PGE or company) relating to the installation and maintenance of the turbine at 16 the Boardman Generating Plant (Boardman or plant), and issued a bench 17 request for additional information about these matters. Since that time I 18 initiated further discovery, generally about the capabilities of the individuals 19 from Siemens and about PGE's oversight and management of installation and 20 maintenance projects. In addition I visited the plant site where I met with the 21 plant management and corporate engineering services personnel involved with 22 the turbine operations and maintenance and reviewed, step by step, the roles 23 and responsibilities of the PGE staff with regards to the turbine. In this

testimony I will provide my interpretation of the company's response to some of
the bench request questions, discuss the results of my recent discovery, and
relate what I learned from my plant visit. Finally I will summarize my position,
on behalf of Staff, on the matter of whether the company prudently installed
and maintained the Boardman turbine.

## Q. FIRST, WHAT WOULD YOU LIKE TO SAY ABOUT THE BENCH REQUEST QUESTIONS?

8 A. One area that the bench request is seeking information on is the installation 9 and maintenance of the LP1 turbine. The first question seeks to find out about 10 Siemens, the original equipment manufacturer (OEM), and its capabilities to 11 install and maintain the turbines they sell. The first question also seeks to 12 discover if using the OEM for post sales installation and servicing as PGE 13 states they have done, is unique in the industry. The company attempts to 14 answer this from a couple of different directions in their bench request 15 response. First Mr. Quennoz, the Vice President of Power Supply, states that 16 it was and is PGE's practice to use an OEM in this way and, based on his 17 experience, standard industry practice also. Although my personal experience 18 is in industrial power plant installations, Mr. Quennoz's response is consistent 19 with my experience, where the OEM was often not only the best source but the 20 only viable source for these services.

Second, the company reports on a survey of 77 other companies
 operating utility scale generation plants in which the companies were asked
 about their use of the turbine OEM. The survey received a rather tepid

1		response with only 13 out of the 77 utilities responding however, of those
2		responding it was common for the companies to involve the OEM in installation
3		and maintenance.
4		When I discussed the capabilities of the OEM with plant management
5		during my recent Boardman visit, Mr. Mayer, the Plant Manager, told me that
6		one recurring topic when he is attends industry gatherings of his peers is the
7		shortage of contractors with the capabilities to perform major turbine
8		maintenance that are not affiliated with an OEM. Finally PGE presented a
9		document showing that Siemens has an active role in large turbine installation
10		and maintenance in the U.S. This OEM has been involved with either
11		performing the maintenance on or providing technical services for more than
12		15 turbine maintenance outages each year for the last several years.
13	Q.	BENCH REQUEST QUESTION TWO REQUESTS COPIES OF OUTAGE
14		REPORTS GENERATED BY SIEMENS FOR TURBINE UPGRADES,
15		MODIFICATIONS, AND REPAIR WORK. WHAT RELEVANCE DO THESE
16		REPORTS HAVE TO THE QUESTION OF PRUDENCE ON THE PART OF
17		PGE IN INSTALLING AND MAINTAINING THE LOW PRESSURE
18		TURBINE?
19	A.	The reports make a good case for the organizational capabilities of the party
20		performing the work, in this case Siemens. The reports document the roles
21		and responsibilities of the contract personnel involved in the outage. There are
22		work scope outlines and details of the actual tasks performed and of the

23 condition of the turbine components as they were found, inspected, and left

1		after the rebuild. In addition the reports have test readings that monitor
2		machine clearances and wear patterns that are important to keeping on top of
3		the ongoing maintenance.
4	Q.	WHAT ABOUT PGE'S ROLE IN THESE OUTAGES AS INDICATED IN THE
5		REPORTS?
6	Α.	The reports list a number of PGE personnel involved in the outage. The
7		Siemens reports do not detail who, from PGE, does what but there are a large
8		number of both plant and corporate PGE staff involved in the outage.
9	Q.	IS THERE ANY WAY TO VERIFY THAT PGE PERSONNEL ARE ACTUALLY
10		INVOLVED IN THE OUTAGES AND NOT JUST CIRCULATED ON THE
11		REPORT?
12	A.	Yes. At my visit to the Boardman plant I requested that one of the PGE staff
13		involved in the outage walk me though how a typical turbine outage was
14		monitored and managed by the company. An engineer from the Boardman
15		plant, Roger Lewis, discussed the way he and others on the PGE staff kept
16		track of turbine maintenance both during the maintenance outages and at other
17		times when a forced outage or other shutdown would allow for a minor repair or
18		adjustment to be made. In addition, Janet Kahl, the head of the PGE corporate
19		mechanical engineering group and project engineer for the Boardman turbine
20		upgrade work, was on hand at the plant visit and discussed corporate office
21		shutdown support.
22	Q.	ARE THERE OTHER BENCH REQUEST QUESTIONS YOU WISH TO

23 COMMENT ON?

Docket UE 196

1	Α.	Yes, question four asks if it is standard practice for a utility to rely exclusively
2		on a contractor's QA/QC program. PGE's response speaks for itself, but I
3		have had personal ISO 9001 QA/QC experience, having managed a machine
4		shop and manufacturing floor under ISO 9001 certification, and would like to
5		elaborate further on this program. First, I can attest to the robust nature of
6		such a quality assurance program. Every step from initial design to parts
7		procurement to assembly included inspection hold points and carefully scripted
8		documentation. Siemens's certification under ISO 9001 gives me no reason to
9		expect their QA/QC was lacking. Second, and again based on personal
10		experience with ISO 9001 certificated, the customer's QA/QC program would
11		not typically be a duplicate of the contractor's program. Rather, the question
12		for them is: "Does the contractor have a robust QA/QC program and
13		demonstrated conformance to the program and does the product/ service
14		conform to the specifications, form and function required by the owner?" In
15		other words, does the turbine start up and run once the installation or
16		maintenance is complete and produce electricity as designed?
17	Q.	DO YOU HAVE ANY FURTHER COMMENTS ON THE BENCH REQUEST
18		QUESTIONS?
19	A.	No.
20	Q.	ARE THERE ANY OTHER POINTS THAT YOU WISH TO DISCUSS?
21	A.	Yes. I performed a cursory investigation on the internet to see what I could find
22		out about industry experience with turbine shaft high cycle fatigue cracking and
23		to see if there are any issues with the shaft metallurgy within the industry.

- Although Siemens has said they have not experienced a similar failure on a
   similar rotor I though it appropriate to see if there were other manufacturers
   that had experienced problems.
- 4

#### Q. WERE YOU ABLE TO LEARN ANYTHING USEFUL?

5 A. No, not really. I learned that the alloy class used in this rotor is considered to 6 be a common choice for this type of application. I learned that, although there 7 is a lot of information about turbine shaft failures on the internet, it is difficult to 8 tease out the exact cause of failures unless it was the result of an obvious 9 excursion such as from an over speed incident. And I learned that there has 10 been quite a lot of investigation and reporting about cracking in turbine rotors of 11 this alloy class. I would summarize my investigation in to the shaft metallurgy 12 issue as follows: It is common for rotors in this type of application to be made 13 of the alloy used in PGE's LP1. It also is not unheard of for rotors constructed 14 of this alloy to experience high cycle fatigue cracking, and high cycle fatigue 15 cracking has been extensively investigated in shafting of this alloy class and 16 found to be most prevalent at higher temperatures than this rotor operates at. 17 Q. WHAT DO YOU THINK THE COMMISSION SHOULD DO ABOUT PGE'S

18

### 19 THEY HAVE DEFERRED IN THIS MATTER?

A. The Commission should allow the amortization to proceed and the company to
 recover the excess power costs plus interest on the unpaid balance as
 requested.

**REQUEST TO AMORTIZE THE PORTION OF EXCESS POWER COSTS** 

23 Q. DO YOU HAVE ANY FURTHER COMMENTS?

Docket UE 196

1 A. No. That concludes my testimony.

#### CERTIFICATE OF SERVICE

#### UE 196

I certify that I have this day served the foregoing document upon all parties of record in this proceeding by delivering a copy in person or by mailing a copy properly addressed with first class postage prepaid, or by electronic mail pursuant to OAR 860-13-0070, to the following parties or attorneys of parties.

Dated at Salem, Oregon, this 6th day of March, 2009.

Kay Barny

Kay Barnes Public Utility Commission Regulatory Operations 550 Capitol St NE Ste 215 Salem, Oregon 97301-2551 Telephone: (503) 378-5763

### UE 196 Service List (Parties)

610 SW BROADWAY - STE 308 PORTLAND OR 97205 catriona@oregoncub.org				
610 SW BROADWAY STE 308 PORTLAND OR 97205 dockets@oregoncub.org				
610 SW BROADWAY STE 308 PORTLAND OR 97205 bob@oregoncub.org				
333 SW TAYLOR - STE 400 PORTLAND OR 97204 mail@dvclaw.com				
REGULATED UTILITY & BUSINESS SECTION 1162 COURT ST NE SALEM OR 97301-4096 stephanie.andrus@state.or.us				
PO BOX 2148 SALEM OR 97308-2148 carla.m.owings@state.or.us				
15160 SW LAIDLAW RD, STE. 110 PORTLAND OR 97229 johnm@pacificenergysystems.com				
PORTLAND GENERAL ELECTRIC				
121 SW SALMON ST 1WTC0702 PORTLAND OR 97204 pge.opuc.filings@pgn.com				
121 SW SALMON 1WTC13 PORTLAND OR 97204 doug.tingey@pgn.com				