



Division 24 Facilities Inspection Progress Reporting Cycle 2008 through 2017 **Due No Later Than March 15, 2018

Operator Information

Operator Name: Canby Utility Board	
Address: 154 NW 1 st Ave. Canby, OR 97013	
Contact: Jim R. Stuart	Title: Operations Manager
Phone: 503-269-4322	Email: jstuart@canbyutility.org
Pole owner <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
If yes, please provide a list of all operators attached to your poles.	

Progress Update for Reporting Cycle January 1, 2008 through December 31, 2017

Did you submit a "5 year check-in report" to the OPUC Safety Staff? Yes No

Did you meet the requirements of OAR 860-0024-0011 for the reporting cycle ending December 31, 2017? Yes No

If not, please file a correction plan for Commission review.

(Staff routinely audits operator records, and conducts field inspections to confirm an operator's inspection/correction process is identifying code violations and correcting them within 2-years.)

** Reminder **

The next ten year cycle is January 1, 2018 through December 31, 2027. You are required to file a report half way through that cycle demonstrating you have conducted detailed inspections of at least 50% of your facilities.

Do you have a plan in place to complete detailed inspections of at least 50% of your facilities by 2023 as required by OAR 860-024-0011.

Yes No

Please submit this completed form, along with the cover sheet, with the Commission Filing Center:

PUC.FilingCenter@state.or.us