## e-FILING REPORT COVER SHEET



Columbia River PUD COMPANY NAME: DOES REPORT CONTAIN CONFIDENTIAL INFORMATION? No Yes If yes, submit a redacted public version (or a cover letter) by email. Submit the confidential information as directed in OAR 860-001-0070 or the terms of an applicable protective order. Select report type: ■ RE (Electric) RG (Gas) RW (Water) RT (Telecommunications) RO (Other, for example, industry safety information) Did you previously file a similar report? Yes, report docket number: OAR 860-024-0011 Report is required by: AR Statute Order Note: A one-time submission required by an order is a compliance filing and not a report (file compliance in the applicable docket) (For example, federal regulations, or requested by Staff) Is this report associated with a specific docket/case? ■ Yes, docket number: RO 11 List Key Words for this report. We use these to improve search results. Safety, Inspections Send the completed Cover Sheet and the Report in an email addressed to PUC.FilingCenter@state.or.us Send confidential information, voluminous reports, or energy utility Results of Operations Reports to PUC Filing Center, PO Box 1088, Salem, OR 97308-1088 or by delivery service to 201 High Street SE Suite 100, Salem, OR 97301.



## **Public Utility Commission**

201 High St SE Suite 100 Salem, OR 97301-3398

Mailing Address: PO Box 1088

Salem, OR 97308-1088 503-373-7394

## Division 24 Facilities Inspection Progress Reporting Cycle 2008 through 2017 \*\*Due No Later Than March 15, 2018



Operator Information				
Operator Name: Columbia River PUD				
Address: 64001 Columbia River Highway, Deer Island, OR 97054				
Contact: Branden Staehely	Title: Engineering Supervisor			
Phone: 503-366-3244	Email: bstaehely@crpud.org			
Pole owner 🛛 Yes 🔲 No				
If yes, please provide a list of all operators attached to your poles.				
	-			
Progress Update for Reporting Cycle January 1, 2008 through December 31, 2017				
Did you submit a "5 year check-in report" to the OPUC Safety Staff? Xes No				
Did you meet the requirements of OAR 860-0024-0011 for the reporting cycle ending December 31, 2017? Xes No				
If not, please file a correction plan for Commission review.				
(Staff routinely audits operator records, and conducts field inspections to confirm an operator's inspection/correction process is identifying code violations and correcting them within 2-years.)				
** Reminder **				
The next ten year cycle is January 1, 2018 through December 31, 2027. You are required to file a report half way through that cycle demonstrating you have conducted detailed inspections of at least 50% of your facilities.				
Do you have a plan in place to complete detailed inspections of at least 50% of your facilities by 2023 as required by OAR 860-024-0011.  Yes No				

Please submit this completed form, along with the cover sheet, with the Commission Filing Center:



64001 Columbia River Highway Deer Island, OR 97054

> Post Office Box 1193 St. Helens, OR 97051

(503) 397-1844 Phone (503) 397-5215 Fax

www.crpud.net facebook.com/crpud twitter.com/crpudUtility

January 3, 2018

Lori Koho, Administrator Public Utility Commission – Safety, Reliability and Security P.O. Box 2148 Salem, OR 97308-2148

## Dear Lori:

The following is a 10-year summary report of the detailed facilities inspections for Columbia River PUD, as required by OAR 860-024-0011(1)(b)(A)(i), for the calendar years 2008 through 2017:

Board of Directors Jake Carter Rob Mathers Craig Melton Harry Price Debbie Reed

General Manager John Nguyen

	OVERHEAD FACILITIES		UNDERGROUND FACILITIES	
YEAR	NUMBER	PERCENTAGE	NUMBER	PERCENTAGE
2008				
2009	2,062	16.4%	72	2.6%
2010	2,029	16.1%	1,744	62.1%
2011	2,062	16.4%	992	35.3%
2012	2,376	19.0%		
2013				
2014	3,206	25.7%		
2015	816	.065%		
TOTAL	12,551	100%	2,808	100%

The "OVERHEAD FACILITIES - NUMBER" refers to the number of poles we have inspected for each year. There are a total of 12,440 poles our system.

The "UNDERGROUND FACILITIES – NUMBER" refers to the number of padmount transformers, vaults, sectionalizing cabinets, secondary pedestals, etc. that we have inspected for each year. We have 2,800 underground facilities in our system.

If you have any questions or need further information, please do not hesitate to contact me at 503-366-3261 or <a href="mailto:bsisco@crpud.org">bsisco@crpud.org</a>.

Brooke Sisco

Sincere

Joint Use Coordinator

Cc: John Nguyen, General Manager

Branden Staehely, Engineering Supervisor