

Douglas Services Inc

Mid cycle Report to Oregon Public Utility Commission on facility inspections

OAR 860-024-011(1)(b)(A)(ii)

From: Todd Way, 541.673.4242 x 1002 , tway@douglasfast.net
Douglas Services Inc.
2350 NE Aviation Dr, Roseburg OR 97470

**This is a summary of the facilities inspection activity for (Owner or Operator name)
For the calendar years 2008 through 2012**

Year	FeederNumber	Percentage
2008	1	8.3%
2009	1	8.3%
2010	1	8.3%
2011	2	16.7%
2012	1	8.3%
totals	6	50.0%

Number refers to number of (poles, customers, attachments, square miles, feeders)
that were inspected during that calendar year.

During the past 5 years DSI has inspected 6 of it's 12 feeder systems.

